

## Helmsman Locker Shelf Fix

Broken shelves in wet specification leisure lockers can make otherwise serviceable lockers look poor, reduce usable storage space and create avoidable maintenance issues. This System 2200 shelf fix specification is designed for repairing damaged, cracked or missing shelves in compatible Helmsman leisure lockers used in swimming pools, gyms, spas, schools and changing room environments.

Manufactured from 5mm white acrylic, the replacement shelf fix offers a clean, moisture-resistant solution for wet area locker repairs. Acrylic is well suited to humid leisure settings because it does not absorb water and is easy to wipe clean. This makes it a practical option when restoring locker interiors affected by wear, impact damage or long-term use.



The standard shelf fix measures 380mm wide x 450mm deep and is made to suit System 2200 leisure locker compartments. Replacing a broken shelf can extend the life of the locker, improve the user experience and avoid the cost of replacing the full locker unit. It is ideal for leisure centres and facilities teams carrying out planned locker maintenance, refurbishment work or reactive repairs.

Custom acrylic shelf sizes are also available for non-standard lockers, older installations and wider locker repair projects.



### **Materials:**

Cast acrylic sheet 5mm thick.

Colour black.